



✓ CERTIFIED

RECOMMENDED FOR NOISY ENVIRONMENTS

HARDWARE

6/6

ONBOARDING

4/4

CONNECTIVITY

1/2

ALERTS

17/17

ACCESSORIES

0/1

SECURITY

2/2

ASSESSMENT

All functionalities of our offers are perfectly functional on this mobile, except for beacon-based indoor localization.

FAILED TESTS:

- **Connectivity** : Beacon detection (45 minutes).

TESTED ACCESSORIES

**B10 REMOTE SOS
BUTTON**

ALERT BUTTONS

VIRTUAL

Huawei FIG LX1

OS 9 Certified on 08/12/2026 By: Benjamin

✓ CERTIFIED

RECOMMENDED FOR NOISY ENVIRONMENTS

HARDWARE

6 / 6

ONBOARDING

4 / 4

CONNECTIVITY

1 / 2

ALERTS

17 / 17

SECURITY

2 / 2

N°	CATEGORY	TEST	TEST RESULT
01	HARDWARE	Phone update	✓
02	HARDWARE	Google Play Protect Certification	✓
03	HARDWARE	Speaker power: sound meter measurement	✓
04	HARDWARE <i>(optional)</i>	Accessibility service persistence (after restart)	✓
05	HARDWARE <i>(optional)</i>	NFC Presence	✓
06	HARDWARE <i>(optional)</i>	NFC Test	✓
07	ONBOARDING	GPS Verification	✓
08	ONBOARDING	Speaker test	✓
09	ONBOARDING	Accelerometer test	✓
10	ONBOARDING <i>(optional)</i>	QR Code Scan	✓
11	CONNECTIVITY <i>(optional)</i>	Bluetooth	✓
12	CONNECTIVITY <i>(optional)</i>	Beacon detection (45 minutes)	✗
13	ALERTS	50cm Fall (X Axis)	✓
14	ALERTS	50cm Fall (Y Axis)	✓
15	ALERTS	50cm Fall (Z Axis)	✓
16	ALERTS	100cm Fall (X Axis)	✓
17	ALERTS	100cm Fall (Y Axis)	✓
18	ALERTS	100cm Fall (Z Axis)	✓
19	ALERTS	Shock	✓
20	ALERTS	Virtual SOS button	✓
21	ALERTS	Sound trigger	✓
22	ALERTS <i>(optional)</i>	Flash trigger	✓
23	ALERTS <i>(optional)</i>	Vibration trigger	✓
24	ALERTS	Immobility	✓
25	ALERTS	Loss of verticality	✓
26	ALERTS	Volume in silent mode	✓
27	ALERTS	Display alerts over other apps	✓
28	ALERTS <i>(optional)</i>	Auto-answer on incoming call	✓
29	ALERTS <i>(optional)</i>	Speaker activation on auto-answer	✓
30	SECURITY	Monitoring persistence despite app closure (1H)	✓
31	SECURITY <i>(optional)</i>	Desktop Mode	✓

TESTED ACCESSORIES

B10 Remote SOS Button : NOK

ALERT BUTTONS

Virtual : OK

ASSESSMENT

All functionalities of our offers are perfectly functional on this mobile, except for beacon-based indoor localization.

FAILED TESTS:

Connectivity : Beacon detection (45 minutes).